

Certificate No: TAP00002GZ

TYPE APPROVAL CERTIFICATE

This is to certify: That the Pipe Couplings

with type designation(s) Repico-G, Repico-S, Repico-SG

Issued to AVK Nederland B.V. Vaassen, Gelderland, Netherlands

is found to comply with

DNV rules for classification – Ships Pt.4 Ch.6 Piping systems DNV-OS-D101 – Marine and machinery systems and equipment, Edition July 2021 DNV class programme DNV-CP-0185 – Type approval – Mechanical joints

Application :

Product(s) approved by this certificate is/are accepted for installation on vessels classed by DNV.

Type:	Temperature range:	Max. working press.:	Sizes:
Repico-G	See page 2	8 bar to 16 bar	DN40 to DN250
Repico-S	See page 2	8 bar to 16 bar	DN40 to DN250
Repico-SG	See page 2	8 bar to 16 bar	DN40 to DN250

Issued at Høvik on 2022-06-02

This Certificate is valid until **2027-06-01**. DNV local station: **Netherlands CMC**

Approval Engineer: Andreas Hansen

for DNV

Zeinab Sharifi Head of Section

LEGAL DISCLAIMER: Unless otherwise stated in the applicable contract with the holder of this document, or following from mandatory law, the liability of DNV AS, its parent companies and their subsidiaries as well as their officers, directors and employees ("DNV") arising from or in connection with the services rendered for the purpose of the issuance of this document or reliance thereon, whether in contract or in tort (including negligence), shall be limited to direct losses and under any circumstance be limited to 300,000 USD.



This Certificate is subject to terms and conditions overleaf. Any significant change in design or construction may render this Certificate invalid. The validity date relates to the Type Approval Certificate and not to the approval of equipment/systems installed.



Product description

Three slip-type pipe expansion joints, with inside rubber sleeve covering the metallic part, tightened with bolts. Tightness is obtained by friction between rubber sleeve and pipe surface.

Repico G – Axial restrained Repico S – Axial flexible Repico SG – Axial flexible / Axial restrained

Materials of construction:

Туре	Repico G	Repico S	Repico SG
Body	AISI 316L	AISI 316L	AISI 316L
Slide plate	AISI 316L	AISI 316L	AISI 316L
Fasteners	SS316 / PTFE coated	SS316 / PTFE coated	SS316 / PTFE coated
Grip	SS301H	-	SS301H
Sealing	EPDM/NBR	EPDM/NBR	EPDM/NBR

Application/Limitation

The slip-on joints covered by this certificate are allowed in class II and class III piping systems, in the below applications

es					
int > 60°C)					
,					
ntial)					
other machinery					
spaces provided the joints are located in easily visible and accessible positions					
Above free board deck only					
In pump rooms and open decks					
Slip joints allowed provided that they are restrained on the pipes, may be used for pipes on deck with a					

The couplings covered by this certificate shall not be used in systems subject to pressure pulsation and/or vibration may occur.

	Size			Repico-G			Repico-S		F	Repico-SG	6
DN	Pipe C DIN/ISO [mm]	D.D. ASTM [Inch]	Length [mm]	Thck. [mm]	MAWP [bar]	Length [mm]	Thck. [mm]	MAWP [bar]	Length [mm]	Thck. [mm]	MAWP [bar]
40	48.3	1.90	60	0.8	16	60	0.8	16	60	0.8	16
50	60.3	2.38	80	1.0	16	80	1.0	16	80	1.0	16
65	76.1	2.88	80	1.0	14	80	1.0	16	80	1.0	14
80	88.9	3.50	110	1.0	14	110	1.0	16	110	1.0	14
90	101.6	4.00	110	1.5	14	110	1.5	16	110	1.5	14
100	114.3	4.50	110	1.5	14	110	1.5	16	110	1.5	14
125	139.7	5.50	111	1.5	14	111	1.5	14	111	1.5	14
150	168.3	6.63	111	1.5	12	111	1.5	12	111	1.5	12
200	219.1	8.63	150	2.0	8	150	2.0	8	150	2.0	8
250	273.0	10.75	150	2.0	8	150	2.0	8	150	2.0	8

The couplings shall be assembled and mounted according to the manufacturer's instructions.



Design temperature is dependent on the gasket material, as below:

•	ÉPDM*		-30°C to +110°C	
	NBR	:	-25°C to +80°C	
1	بالمقلم مرامات		المحمد مارم معاليه معالم برما مراله	-

*) Material not to be utilized in hydrocarbon applications.

Materials chosen for the specific system shall be suitable for the intended medium and environmental conditions.

Slip-on joints shall not be used in pipelines in cargo holds, tanks, and other spaces which are not easily accessible. Application of the joints inside tanks may be permitted only if the inside medium is the same as that surrounding the coupling. Such application shall be subject to case-by-case approval.

Type Approval documentation

- AVK Couplings and Repair Couplings Catalogue Edition 05-2019 - 74501 REPICO-G Assembly AD 2021-09-15 74520 REPICO-SG Assembly AC 2021-09-15 7470010101012 S-19 platine AC 2021-09-15 7470010100602 S-60 platine AB 2021-09-15 7470010100602 S-60 platine AB 2021-09-15 1BB-2436 Fire test 74501004211101 DN32 PN10 - 2020-11-17 1BB-2438 Fire test 74501004211101 DN32 PN10 - 2021-03-22 - Burst test report Repico-G DN100 EPDM - 2021-03-22 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 EPDM - 2021-03-25 - Use test report Repico-G DN200 EPDM - 2021-03-25 -	Document no.	Title	Rev.	Date
MI 745 - AC AVK Repico Coupling - Mounting instructions Edition 2020 - 74501 REPICO-G Assembly AD 2021-09-15 74520 REPICO-S Assembly AD 2021-09-15 74501 REPICO-S Assembly AD 2021-09-15 74700101011142 S-114 platine AD 2021-09-15 74700100100292 S-20 platine AB 2021-09-15 74700100100202 S-60 platine AB 2021-09-15 1BB-2440 Fire test 745201021911101 DN32 PN10 - 2020-11-17 1BB-2436 Fire test 74520100219111 DN30 PN10 - 2021-117 1BB-2438 Fire test 7452010021911 DN30 PN10 - 2021-117 1BB-2438 Fire test 745201002111 DN30 PN10 - 2021-03-21 - Pull-out test report Repico-G DN100 EPDM - 2021-03-22 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-25 - Burst test report Repico-G DN100 NBR, witnessed by DNV - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021	-	AVK Couplings and Repair Couplings Catalogue Edition 05-2019	-	-
74501 REPICO-G Assembly AD 2021-09-15 74520 REPICO-S Assembly AD 2021-09-15 74521 REPICO-S Assembly AD 2021-09-15 747001001010219 S-219 platine AC 2021-09-15 74700100100002 S-60 platine AB 2021-09-15 747001001000002 S-60 platine AB 2021-09-15 18B-2440 Fire test 7452010211911101 DN20 PN08 - 2020-11-17 18B-2438 Fire test 745200089111 DN80 PN10 - 2020-11-17 18B-2438 Fire test 745200089111 DN80 PN10 - 2021-03-21 - Burst test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 NBR - 2021-03-22 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021-03-25 - Vacuum test report Repico-G DN200 EPDM - 2021-03-25 <td>MI 745 – AC</td> <td>AVK Repico Coupling – Mounting instructions Edition 2020</td> <td>-</td> <td>-</td>	MI 745 – AC	AVK Repico Coupling – Mounting instructions Edition 2020	-	-
74520 REPICO-S Assembly AD 2021-09-15 74552 REPICO-SG Assembly AC 2021-09-15 74700101012192 S-219 platine AB 2021-09-15 747001000002 S-60 platine AB 2021-09-15 7470010010002 S-60 platine AB 2021-11-17 IBB-2436 Fire test 745201004211101 DN200 PN08 - 2020-11-17 IBB-2436 Fire test 745201004211101 DN200 PN08 - 2020-11-17 IBB-2436 Fire test 74520100421110 DN30 PN10 - 2020-11-17 IBB-2438 Fire test 74520100421110 DN30 PN10 - 2020-11-17 IBB-2438 Fire test 74520100421101 DN30 PDM, witnessed by DNV - 2021-03-21 - Pull-out test report Repico-G DN100 EPDM - 2021-03-25 - Tightness test report Repico-G DN100 PDM - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021-03-25 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Burst test report Repico-G DN200 EPDM -<	74501	REPICO-G Assembly	AD	2021-09-15
74552 REPICO-SG Assembly AD 2021-09-15 7470010110142 S-114 platine AC 2021-09-15 74700100102602 S-219 platine AB 2021-09-15 BB-2440 Fire test 745201021911101 DN20 PN08 - 2020-11-17 IBB-2440 Fire test 745201021911101 DN32 PN10 - 2020-11-17 IBB-2443 Fire test 745201021911101 DN32 PN10 - 2021-09-15 - Burst test report Repico-G DN100 EPDM, witnessed by DNV - 2021-09-15 - Burst test report Repico-G DN100 EPDM - 2021-09-16 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-21 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021-03-25 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021-03-25 - Tightness test	74520	REPICO-S Assembly	AD	2021-09-15
74700101101142 S-114 platine AC 2021-09-15 74700100100602 S-60 platine AB 2021-09-15 74700100100602 S-60 platine AB 2021-09-15 1BB-2436 Fire test 745201021911101 DN200 PN08 - 2020-11-17 1BB-2438 Fire test 745200089111 DN80 PN10 - 2020-11-17 1BB-2438 Fire test 745200089111 DN80 PN10 - 2021-03-15 - Pull-out test report Repico-G DN100 EPDM - 2021-03-22 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 EPDM - 2021-03-22 - Vacuum test report Repico-G DN100 NBR, witnessed by DNV - 2021-03-25 - Burst test report Repico-G DN200 EPDM, witnessed by DNV - 2021-03-25 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25 - Tightness test report Repico-G DN200 NBR - 2021-03-25 - Uset test report Repico-G DN200 NBR - 2021-03-25 <	74552	REPICO-SG Assembly	AD	2021-09-15
74700100102192 S-219 platine AB 2021-09-15 74700100100002 S-60 platine AB 2021-09-15 IBB-2440 Fire test 745201021911101 DN20 PN08 - 2020-11-17 IBB-2436 Fire test 7450004211101 DN32 PN10 - 2020-11-17 IBB-2438 Fire test 74520089111 DN80 PN10 - 2020-11-17 IBB-2438 Fire test 74520089111 DN80 PN10 - 2021-03-21 - Burst test report Repico-G DN100 EPDM - 2021-03-22 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 EPDM - 2021-03-25 - Tightness test report Repico-G DN100 NBR, witnessed by DNV - 2021-03-25 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Tightness test report Repico-G DN200 NBR - 2021-03-25 - Tightness test report Repico-G DN200 NBR - 2021-03-25 - Tigh	74700101101142	S-114 platine	AC	2021-09-15
74700100100602 S-60 platine AB 2021-09-15 IBB-2440 Fire test 745201021911101 DN20 PN08 - 2020-11-17 IBB-2436 Fire test 74520102411101 DN32 PN10 - 2020-11-17 IBB-2438 Fire test 745200089111 DN30 PN10 - 2020-11-17 - Burst test report Repico-G DN100 EPDM, witnessed by DNV - 2021-03-21 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Vacuum test report Repico-G DN100 EPDM - 2021-03-22 - Vacuum test report Repico-G DN100 NBR, witnessed by DNV - 2021-03-25 - Burst test report Repico-G DN100 NBR - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021-03-25 - Burst test report Repico-G DN200 NBR - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25 - <	74700100102192	S-219 platine	AB	2021-09-15
IBB-2440 Fire test 745201021911101 DN20 PN08 - 2020-11-17 IBB-2436 Fire test 745200089111 DN80 PN10 - 2020-11-17 IBB-2438 Fire test 745200089111 DN80 PN10 - 2021-09-01 - Burst test report Repico-G DN100 EPDM, witnessed by DNV - 2021-03-21 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 EPDM - 2021-03-22 - Vacuum test report Repico-G DN100 EPDM - 2021-03-22 - Burst test report Repico-G DN100 EPDM - 2021-03-25 - Burst test report Repico-G DN200 EPDM, witnessed by DNV - 2021-03-25 - Burst test report Repico-G DN200 EPDM - 2021-03-25 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Vacuum test report Repico-G DN200 EPDM - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25	74700100100602	S-60 platine	AB	2021-09-15
IBB-2436 Fire test 74501004211101 DN32 PN10 - 2020-11-17 IBB-2438 Fire test 745200089111 DN80 PN10 - 2021-03-21 - Burst test report Repico-G DN100 EPDM, witnessed by DNV - 2021-03-21 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 EPDM - 2021-03-22 - Vacuum test report Repico-G DN100 EPDM - 2021-03-25 - Burst test report Repico-G DN100 NBR, witnessed by DNV - 2021-03-25 - Burst test report Repico-G DN200 EPDM, witnessed by DNV - 2021-03-25 - Tightness test report Repico-G DN200 EPDM - 2021-03-25 - Vacuum test report Repico-G DN200 EPDM - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25 - Vacuum test report Repico-G DN200 NBR - 2021-03-25 - Tightness test report Repico-G DN200 NBR - 2021-03-25	IBB-2440	Fire test 745201021911101 DN200 PN08	-	2020-11-17
IBB-2438 Fire test 745200089111 DN80 PN10 - 2020-11-17 - Burst test report Repico-G DN100 EPDM, witnessed by DNV - 2021-03-21 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-21 - Repeated assembly test report Repico-G DN100 EPDM - 2021-03-22 - Tightness test report Repico-G DN100 EPDM - 2021-03-25 - Wacuum test report Repico-G DN100 NBR - 2021-03-25 - Burst test report Repico-G DN200 EPDM, witnessed by DNV - 2021-03-25 - Tightness test report Repico-G DN200 EPDM, witnessed by DNV - 2021-03-25 - Tightness test report Repico-G DN200 EPDM, witnessed by DNV - 2021-03-25 - Vacuum test report Repico-G DN200 NBR, witnessed by DNV - 2021-03-25 - Tightness test report Repico-G DN200 NBR - 2021-03-25 - Vacuum test report Repico-G DN50 EPDM - 2021-03-25 - Pull-out test report Repico-G DN50 EPDM - 2021-03-25 - Vacuum test report Repico-G DN50 NBR <	IBB-2436	Fire test 74501004211101 DN32 PN10	-	2020-11-17
Image: constraint of the second sec	IBB-2438	Fire test 745200089111 DN80 PN10	-	2020-11-17
Image: constraint of the second sec	-	Burst test report Repico-G DN100 EPDM, witnessed by DNV	-	2021-09-01
Repeated assembly test report Repico-G DN100 EPDM2021-03-22Tightness test report Repico-G DN100 EPDM2021-03-25Burst test report Repico-G DN100 EPDM2021-03-25Burst test report Repico-G DN100 NBR, witnessed by DNV2021-03-25Burst test report Repico-G DN200 EPDM, witnessed by DNV2021-03-25Utightness test report Repico-G DN200 EPDM2021-03-25Utightness test report Repico-G DN200 EPDM2021-03-25Utightness test report Repico-G DN200 EPDM2021-03-25Utightness test report Repico-G DN200 NBR2021-03-25Utightness test report Repico-G DN50 EPDM2021-03-25Utightness test report Repico-G DN50 EPDM2021-03-22Utightness test report Repico-G DN50 EPDM2021-03-22Utightness test report Repico-G DN50 EPDM2021-03-22Utightness test report Repico-G DN50 EPDM2021-03-25Utightness test report Repico-G DN50 NBR2021-03-25Utightness test report Repico-G DN50 NBR2021-03-25Utightness test report Repico-S DN100 EPDM2021-03-25Utightness test report Repico-S DN100 EPDM	-	Pull-out test report Repico-G DN100 EPDM	-	2021-03-21
-Tightness test report Repico-G DN100 EPDM-2021-03-22-Vacuum test report Repico-G DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-G DN200 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-G DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN200 EPDM-2021-03-25-Vacuum test report Repico-G DN200 EPDM-2021-03-25-Burst test report Repico-G DN200 EPDM-2021-03-25-Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN200 NBR-2021-03-25-Burst test report Repico-G DN50 EPDM-2021-03-22-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-25-Burst test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR<	-	Repeated assembly test report Repico-G DN100 EPDM	-	2021-03-22
-Vacuum test report Repico-G DN100 EPDM-2021-03-25-Burst test report Repico-G DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-G DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN200 EPDM-2021-03-25-Vacuum test report Repico-G DN200 EPDM-2021-03-25-Vacuum test report Repico-G DN200 EPDM-2021-03-25-Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN200 NBR-2021-03-25-Tightness test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN50 PDM-2021-03-25-Pull-out test report Repico-G DN50 EPDM-2021-03-25-Vacuum test report Repico-G DN50 EPDM-2021-03-25-Vacuum test report Repico-G DN50 EPDM-2021-03-25-Uvacuum test report Repico-G DN50 NBR-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Uvacuum test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Uvacuum test report Repico-S DN100 NBR-2021-03-25-Uvacuum test report Repico-S DN100 NBR-2021-03	-	Tightness test report Repico-G DN100 EPDM	-	2021-03-22
-Burst test report Repico-G DN100 NBR, witnessed by DNV-2021-09-01-Tightness test report, Repico-G DN200 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-G DN200 EPDM-2021-03-25-Vacuum test report Repico-G DN200 EPDM-2021-03-25-Burst test report Repico-G DN200 EPDM-2021-03-25-Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25-Vacuum test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN50 EPDM-2021-03-25-Burst test report Repico-G DN50 EPDM-2021-03-22-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-25-Burst test report Repico-G DN50 EPDM-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Burst test report Repico-G DN50 NBR-2021-03-25-Burst test report Repico-G DN50 NBR-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-<	-	Vacuum test report Repico-G DN100 EPDM	-	2021-03-25
Image: constraint of the second sec	-	Burst test report Repico-G DN100 NBR, witnessed by DNV	-	2021-09-01
Burst test report Repico-G DN200 EPDM, witnessed by DNV-2021-03-25Vacuum test report Repico-G DN200 EPDM-2021-03-25Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25Vacuum test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25Vacuum test report Repico-G DN200 NBR-2021-03-25Vacuum test report Repico-G DN200 NBR-2021-03-25Vacuum test report Repico-G DN50 EPDM, witnessed by DNV-2021-03-25Pull-out test report Repico-G DN50 EPDM-2021-03-22Vacuum test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25Uacuum test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25Uacuum test report Repico-G DN50 NBR-2021-03-25Uacuum test report Repico-S DN100 EPDM-2021-03-25Uacuum test report Repico-S DN200 EPDM-2021-03-25Uacuum test report Repico-S DN200 EPDM-2021-03-25	-	Tightness test report, Repico-G DN100 NBR	-	2021-03-25
-Tightness test report Repico-G DN200 EPDM-2021-03-25-Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN200 NBR-2021-03-25-Burst test report Repico-G DN50 EPDM-2021-03-25-Burst test report Repico-G DN50 EPDM-2021-03-25-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 NBR-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Surst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25 <t< td=""><td>-</td><td>Burst test report Repico-G DN200 EPDM, witnessed by DNV</td><td>-</td><td>2021-03-25</td></t<>	-	Burst test report Repico-G DN200 EPDM, witnessed by DNV	-	2021-03-25
-Vacuum test report Repico-G DN200 EPDM-2021-03-25-Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN200 NBR-2021-03-25-Burst test report Repico-G DN50 EPDM, witnessed by DNV-2021-03-22-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Vacuum test report Repico-S DN100 NBR-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPD	-	Tightness test report Repico-G DN200 EPDM	-	2021-03-25
-Burst test report Repico-G DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN200 NBR-2021-03-25-Burst test report Repico-G DN50 EPDM, witnessed by DNV-2021-03-22-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-G DN50 NBR-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Surst test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN100 NBR-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Usen test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM	-	Vacuum test report Repico-G DN200 EPDM	-	2021-03-25
-Tightness test report Repico-G DN200 NBR-2021-03-25-Vacuum test report Repico-G DN50 EPDM, witnessed by DNV-2021-03-22-Burst test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Burst test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Surst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Re	-	Burst test report Repico-G DN200 NBR, witnessed by DNV	-	2021-03-25
-Vacuum test report Repico-G DN200 NBR-2021-03-25-Burst test report Repico-G DN50 EPDM, witnessed by DNV-2021-03-22-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Burst test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 NBR-	-	Tightness test report Repico-G DN200 NBR	-	2021-03-25
-Burst test report Repico-G DN50 EPDM, witnessed by DNV-2021-03-22-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Burst test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Surst test report Repico-S DN200 EPDM-2021-03-25-Surst test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Surst test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico-S DN200	-	Vacuum test report Repico-G DN200 NBR	-	2021-03-25
-Pull-out test report Repico-G DN50 EPDM-2021-03-22-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 NBR-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Tightness test report	-	Burst test report Repico-G DN50 EPDM, witnessed by DNV	-	2021-03-22
-Tightness test report Repico-G DN50 EPDM-2021-03-22-Vacuum test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 NBR-2021-03-25-Tightness test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Durst test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico	-	Pull-out test report Repico-G DN50 EPDM	-	2021-03-22
-Vacuum test report Repico-G DN50 EPDM-2021-03-22-Burst test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Burst test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN5	-	Tightness test report Repico-G DN50 EPDM	-	2021-03-22
-Burst test report Repico-G DN50 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-G DN50 NBR-2021-03-25-Burst test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200-2021-03-25-Vacuum test report Re	-	Vacuum test report Repico-G DN50 EPDM	-	2021-03-22
-Tightness test report Repico-G DN50 NBR-2021-03-25-Vacuum test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 EPDM-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200-2021-03-25-Uacuum test report Repico-S DN200-2021-03-25-Uacuum test report Repico-S DN200<	-	Burst test report Repico-G DN50 NBR, witnessed by DNV	-	2021-03-25
-Vacuum test report Repico-G DN50 NBR-2021-03-25-Burst test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-22-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200-2021-03-25-Uacuum test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Uacuum test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Uacu	-	Tightness test report Repico-G DN50 NBR	-	2021-03-25
-Burst test report Repico-S DN100 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-22-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200-2021-03-25-Uacuum test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Uacuum test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM-2021-03-22-<	-	Vacuum test report Repico-G DN50 NBR	-	2021-03-25
-Tightness test report Repico-S DN100 EPDM-2021-03-25-Vacuum test report Repico-S DN100 EPDM-2021-03-22-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200-2021-03-25-Uacuum test report Repico-S DN200-2021-03-25-Burst test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM-2021-03-22-Tightness test report Repico-S DN50 EPDM-2021-03-22	-	Burst test report Repico-S DN100 EPDM, witnessed by DNV	-	2021-03-25
-Vacuum test report Repico-S DN100 EPDM-2021-03-22-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN200 NBR-2021-03-25-Uacuum test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-25-Uacuum test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM-2021-03-22	-	Tightness test report Repico-S DN100 FPDM	-	2021-03-25
-Burst test report Repico-S DN100 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200 NBR-2021-03-25-Burst test report Repico-S DN200-2021-03-25-Vacuum test report Repico-S DN200-2021-03-25-Uacuum test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22	-	Vacuum test report Repico-S DN100 EPDM	-	2021-03-22
-Tightness test report Repico-S DN100 NBR-2021-03-25-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200-2021-03-25-Vacuum test report Repico-S DN200-2021-03-25-Uset test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-25-Burst test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22	-	Burst test report Repico-S DN100 NBR, witnessed by DNV	_	2021-03-25
-Burst test report Repico-S DN200 EPDM, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 EPDM-2021-03-25-Vacuum test report Repico-S DN200 EPDM-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Burst test report Repico-S DN200 NBR, witnessed by DNV-2021-03-25-Tightness test report Repico-S DN200 NBR-2021-03-25-Vacuum test report Repico-S DN200-2021-03-25-Vacuum test report Repico-S DN200-2021-03-25-Burst test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM, witnessed by DNV-2021-03-22-Tightness test report Repico-S DN50 EPDM-2021-03-22	-	Tightness test report Repico-S DN100 NBR	_	2021-03-25
- Tightness test report Repico-S DN200 EPDM - 2021-03-25 - Vacuum test report Repico-S DN200 EPDM - 2021-03-25 - Burst test report Repico-S DN200 NBR, witnessed by DNV - 2021-03-25 - Tightness test report Repico-S DN200 NBR, witnessed by DNV - 2021-03-25 - Tightness test report Repico-S DN200 NBR - 2021-03-25 - Vacuum test report Repico-S DN200 - 2021-03-25 - Vacuum test report Repico-S DN200 - 2021-03-25 - Burst test report Repico-S DN50 EPDM, witnessed by DNV - 2021-03-25 - Burst test report Repico-S DN50 EPDM, witnessed by DNV - 2021-03-22 - Tightness test report Repico-S DN50 EPDM - 2021-03-22	-	Burst test report Repico-S DN200 EPDM, witnessed by DNV	_	2021-03-25
- Vacuum test report Repico-S DN200 EPDM - 2021-03-25 - Burst test report Repico-S DN200 NBR, witnessed by DNV - 2021-03-25 - Tightness test report Repico-S DN200 NBR - 2021-03-25 - Tightness test report Repico-S DN200 NBR - 2021-03-25 - Vacuum test report Repico-S DN200 - 2021-03-25 - Burst test report Repico-S DN50 EPDM, witnessed by DNV - 2021-03-25 - Burst test report Repico-S DN50 EPDM, witnessed by DNV - 2021-03-22 - Tightness test report Repico-S DN50 EPDM - 2021-03-22	-	Tightness test report Repice-S DN200 EPDM	_	2021-03-25
- Burst test report Repico-S DN200 NBR, witnessed by DNV - 2021-03-25 - Tightness test report Repico-S DN200 NBR - 2021-03-25 - Vacuum test report Repico-S DN200 - 2021-03-25 - Burst test report Repico-S DN200 - 2021-03-25 - Burst test report Repico-S DN50 EPDM, witnessed by DNV - 2021-03-22 - Tightness test report Repico-S DN50 EPDM - 2021-03-22 - Tightness test report Repico-S DN50 EPDM - 2021-03-22	-	Vacuum test report Repico-S DN200 EPDM	_	2021-03-25
- Tightness test report Repico-S DN200 NBR - 2021-03-25 - Vacuum test report Repico-S DN200 - 2021-03-25 - Burst test report Repico-S DN50 EPDM, witnessed by DNV - 2021-03-22 - Tightness test report Repico-S DN50 EPDM - 2021-03-22 - Tightness test report Repico-S DN50 EPDM - 2021-03-22	-	Burst test report Repico-S DN200 NBR witnessed by DNV	_	2021-03-25
- Vacuum test report Repico-S DN200 - 2021-03-25 - Burst test report Repico-S DN50 EPDM, witnessed by DNV - 2021-03-22 - Tightness test report Repico-S DN50 EPDM - 2021-03-22	-	Tightness test report Repico-S DN200 NBR	_	2021-03-25
Burst test report Repico-S DN50 EPDM, witnessed by DNV 2021-03-22 Tightness test report Repico-S DN50 EPDM 2021-03-22	-	Vacuum test report Repico-S DN200	_	2021-03-25
- Tightness test report Repico-S DN50 EPDM - 2021-03-22	-	Burst test report Repico-S DN50 EPDM witnessed by DNV	-	2021-03-22
	-	Tightness test report Repico-S DN50 EPDM	-	2021-03-22
- Vacuum test report Repice-S DN100 EPDM - 2021-03-22	-	Vacuum test report Repico-S DN100 EPDM		2021-03-22
- Burst test report Repice-S DN50 NBR_witnessed by DNV - 2021-03-25	-	Burst test report Repico-S DN50 NBR witnessed by DNV	-	2021-03-25
- Tightness test report Repice-S DN50 NBR - 2021-03-25	-	Tightness test report Repico-S DN50 NBR	-	2021-03-25



Document no.	Title	Rev.	Date
-	Vacuum test report Repico-S DN50 NBR	-	2021-03-25
-	Burst test report Repico-SG DN100 EPDM, witnessed by DNV	-	2021-03-25
-	Tightness test report Repico-SG DN100 EPDM	-	2021-03-25
-	Vacuum test report Repico-SG DN100 EPDM	-	2021-03-22
-	Burst test report Repico-SG DN200 EPDM, witnessed by DNV	-	2021-03-25
-	Tightness test report Repico-S DN200 EPDM	-	2021-03-25
-	Vacuum test report Repico-SG DN200 EPDM	-	2021-03-25
-	Burst test report, Repico-SG DN50 EPDM, witnessed by DNV	-	2021-03-22
-	Tightness test report Repico-SG DN50 EPDM	-	2021-03-22
-	Vacuum test report Repico-SG DN50 EPDM	-	2021-03-22

Tests carried out

Tightness test, repeated assembly test, burst test, vacuum test, pull-out test, and fire test.

Marking of product

For traceability to this type approval, each product is at least to be marked clearly with:

- Manufacturer's name or trademark
- Type designation

The identification marking shall be in low stressed areas.

Periodical assessment

For retention of the Type Approval, a DNV surveyor shall perform periodical assessment after two years (+/- 90 days) and after 3.5 years (+/- 90 days) to verify that the conditions for the approval are complied with. Reference is made to DNV-CP-0338.